

FLAME RETARDANT · ACID RESISTANT · WINTER

D59 FLAME & ACID WINTER JACKET

SANS
434

DESCRIPTION

Vulcan Workwear's Flame Acid Winter Jacket is a locally produced, high-quality solution for protecting users from accidental flame contact and acid splashes while keeping them warm in colder work environments. Heavy-duty D59 drill fabric with flame acid treatment technology offers reliable protection, with a removable hood and adjustable cuffs for versatility. Approved to the latest SANS 434 specification with SABS permit marking.

FEATURES

- Collared jacket with internal hanger loop and removable hood
- High-visibility FR reflective tape on arms
- Concealed heavy-duty Vizlon zip with plastic press stud closure
- 2 below-chest pockets and 1 left chest pocket
- Adjustable sleeve cuffs with 2-position fastening and capped press studs
- Double needle topstitching on shoulder and armhole seams
- FR & acid resistant embroidery on arm

SUITABLE INDUSTRIES

ENGINEERING SMELTING MINING CONSTRUCTION

OIL & GAS PETROLEUM MAINTENANCE WELDING



SPECIFICATIONS

SKU	90/060/NV/WINT/JKT
STYLE	3-pocket long sleeve thermal jacket, double lined for warmth
OUTER	100% cotton, 320gsm FR fabric
INTERLINING	100gsm FR wadding
LINING	100% cotton, 220gsm FR fabric
TAPE	50mm silver FR tape on arms
COLOUR	Navy Blue
ACID TESTING	HCl 32%, H ₂ SO ₄ 24%, HNO ₃ 65%, NaOH 40%
STANDARDS	SANS 434 · 1387-4 · 1362 · 1822 · 5278 · 10235 · 50471

CARE & MAINTENANCE

- Wash flame retardant garments separately from non-flame-retardant clothing
- Avoid Hypochlorite bleach and detergents containing it
- Avoid direct sunlight exposure – fading may occur
- Pre-treat greasy stains and wash in warm water with a light cleaning solvent
- Do not tumble dry; rinse thoroughly to remove wetting agents
- Iron to enhance and regenerate the finish effect; never iron on reflective tape

WARM WASH

NO BLEACH

DO NOT TUMBLE DRY

COOL IRON

DRY CLEANABLE

